

## Safety Advisory Notice

To helicopter pilots and operators

Number: AO-2020-040-SAN-01

# Correctly fitted, secured and maintained flight helmets can save lives

A correctly fitted and secured flight helmet can significantly reduce injuries and save lives in the event of a serious incident or accident. But a helmet is only fully effective if it is fitted correctly, retained securely on the wearer's head, and maintained in accordance with the manufacturer's instructions.

#### What happened

On 31 July 2020, the pilot of a Robinson R44 helicopter was conducting aerial spraying along a property fence line. During the fifth spray load, as the helicopter descended from above trees to recommence spraying, it struck a powerline about 5 metres above the ground. The helicopter subsequently collided with terrain resulting in substantial damage. The pilot sustained fatal injuries.



#### Source: ATSB

#### Survivability

The pilot was not adequately restrained by the seat belt's shoulder sash resulting in the

pilot's head impacting on the left side of the helicopter. This resulted in non-survivable head injuries.

The pilot was wearing a helmet during the initial impact. While it could not be determined if the accident impact forces were survivable, the helmet may not have been fully effective as it came off during the accident sequence.

There was also no evidence that the helmet had been maintained or serviced, including after it had likely been worn in a previous accident.

### Helmet regulations and standards

For all pilots conducting low-level operations, a helmet is an essential component of personal protective equipment required to be worn under work, health and safety guidelines. Wearing a helmet is not mandated by the Civil Aviation Safety Authority, and there is no Australian Standard for flight helmets. However, many commercially available helmets meet or exceed military and US and European civilian standards, some of which are designed specifically for helicopter operations.

To work as designed, a helmet must be adjusted to fit the head and the chin strap must be fastened securely. The helmet must be serviced regularly, routinely inspected for damage, and replaced immediately if it has sustained a major impact.

#### Safety advisory notice

**AO-2020-040-SAN-01:** The ATSB strongly encourages all pilots conducting low-level operations to wear a flight helmet, ensuring that it is:

fit for purpose



## **Safety Advisory Notice**

To helicopter pilots and operators

Number: AO-2020-040-SAN-01

Released: March 2022

- **Australian Transport Safety Bureau** 
  - properly secured by using the chin strap

custom fitted to the pilot's head

• maintained in accordance with the manufacturer's recommendations.

Read more about the ATSB's investigation:

http://www.atsb.gov.au/publications/investigation\_reports/2020/aair/ao-2020-040